

Erosion / Corrosion Resistant Coatings for Compressor Airfoils



Presented by
Mr. Greg Kilchenstein
OSD, Maintenance

29 August 2012

Report Documentation Page				Form Approved OMB No. 0704-0188	
Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.					
1. REPORT DATE 29 AUG 2012		2. REPORT TYPE		3. DATES COVERED 00-00-2012 to 00-00-2012	
4. TITLE AND SUBTITLE Erosion / Corrosion Resistant Coatings for Compressor Airfoils				5a. CONTRACT NUMBER	
				5b. GRANT NUMBER	
				5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)				5d. PROJECT NUMBER	
				5e. TASK NUMBER	
				5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Office of the Deputy Assistant Secretary of Defense for Maintenance ,3500 Defense Pentagon,Washington,DC,20301				8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)	
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited					
13. SUPPLEMENTARY NOTES ASETSDefense 2012: Sustainable Surface Engineering for Aerospace and Defense Workshop, August 27-30, 2012, San Diego, CA. Sponsored by SERDP/ESTCP.					
14. ABSTRACT					
15. SUBJECT TERMS					
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT Same as Report (SAR)	18. NUMBER OF PAGES 18	19a. NAME OF RESPONSIBLE PERSON
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified			



The Problem


- DoD Maintenance cost \$84B in 2010
- Gas Turbine Engine Mx costs exceeded \$7.5B in 2010
- Low Power accounts for \approx half unscheduled removals
- Engine erosion a leading contributor to low power
- Compressor airfoil corrosion major MRO cost driver
- DoD consumes \approx \$13B in aviation fuel annually
- Eroded engines emit 10 to 25% greater pollutants






The Problem

GAS TURBINE ENGINE




**Erosion of
compressor
blades**



Actual results from engine test



Typical Erosion Mechanism



Gem for Lynx



T64 for H-53



T58 for H-46



Gnome for Sea King



T55 for MH-47



AE1107 for V-22



T700 for H-60

Platforms in
Production



Platforms in
Evaluation / Qualification



AGT1500 for M1A Tank



RTM322 for Merlin

Arriel for LUH

GE38 for H-53K



CF6 for B767

JT8D for MD-88

Makila
for Super Puma/Cougar

Honeywell
HPW3000



Pratt & Whitney
A United Technologies Company



T56 for C-130



CFM56 for
B737



CF34 for E170




CFM56 for
B737 / A320





CH-53 Engine Test Results

T64 Engine Sand Ingestion Test






CH-53 Engine in Desert Ops

- T64 engine overhaul costs \$750,000; 771 engines in fleet
- > 1,000 T64 engine compressor sets coated since 2003
- > 750,000 operational hours in-theatre
- Uncoated TOW \approx 113 hrs; Coated TOW \approx 1100 hrs¹
- H-53/T64 readiness rates consistently met during OIF/OEF
 - Compared to numerous bare firewalls during Desert Storm
- PMA 261 calculated \$120M cost avoidance in 2005²



¹ First 60 uncoated vs first 60 coated in OIF



Uncoated engine
at 113 hours
 \approx 3 months
Time-On-Wing




Coated engine
at 2,023 hours
40 months
Time-On-Wing

² Based on reduced frequency of engine repair only, concurrent airfoil replacement and other logistics elements not considered 7



CH-46 Engine in Desert Ops

- Blade coating initiated in 2005 to enhance durability and TOW
- 19 Uncoated engine blade failures (2003-2007); 2 class A Mishaps (2005 & 2008)
- Zero Coated engine blade failures, Coating mandated for Safety of Flight
- > 500 T58 engine compressor sets coated since 2005
- > 250,000 operational hours in-theatre; T58 overhaul cost \approx \$285K
- Uncoated engine average TOW \approx 530 hrs¹
- Coated engine average TOW \approx 798 hrs¹
- Sand Ingestion Testing demonstrates 3% reduction in fuel consumption



¹ Based on PMA-226 engine study data

² Based on reduced frequency of engine repair only, concurrent airfoil replacement and other logistics elements not considered



T56 Performance Summary

Uncoated vs Coated Engine

Uncoated Engine (April – May 2011)

With “sand turbine” at San Antonio:

~ 104% shp at START

~ 95% after ~ 70 lbs sand ingested

~ 80% after 135 lbs sand ingested

With reference turbine at Winnipeg:

~ 88% shp after 135 lbs sand ingested

Coated Engine (July – Oct 2011)

With “sand turbine” at San Antonio:

~ 102.5% shp at START

~ 95% after ~ 110 lbs sand ingested

~ 91% after 135 lbs sand ingested

With reference turbine at Winnipeg:

~ 97.5% shp after 135 lbs sand ingested

~ 12% less specific fuel consumption



Coated Engine

1,000 hours > TSO

~ 3X power retention

2-3% Corrected Fuel Flow

1-2% Specific Fuel Consumption


decrease @ 95% shp





6th Stage Blade @ 135 lbs Sand Ingested


Pressure Side



2005, Depot Induction




2011
135 lbs SITE



2011
135 lbs SITE



6th Stage Blade @ 135 lbs Sand Ingested






6th Stage Blade @ 135 lbs Sand Ingested





Post-Test Surface Finish



Retaining low surface finish contributes to lower fuel consumption

Pressure Side (PS)
Roughness Average (μ-in)
Uncoated Engine = 45
Uncoated Ref Blades = 42.9
Coated = 18.4


135 lbs sand consumed
90% ARD A4: 10% C-Spec



Commercial Aero Fuel Savings



Chord Loss Testing Commercial Turbopfan




$\approx 0.5\%$ to 2.0% SFC impact on
Commercial Turbopfan
pending areas of operation



Thickness Impact Leading Edge Configuration


■ Thinning of Eroded Blade

Blade after 2 cycles
or $\approx 4\%$ chord loss







Uncoated vs Coated Compressor Stage Corrosion Test



14 days exposure 5% Salt Fog
per B117 Test Standard



Operations



H-53



C-130



H-60



V-22



H-47

Impact on Engines No Coating



113 hrs \approx 3 months
Time-On-Wing



Blade Curling \Rightarrow
Blade Failure

- Low engine power
 - Eroded / Corroded blades
- \downarrow
- Unscheduled Removals
 - Increased Field and Depot Maintenance
 - Increased compressor airfoil scrap rates
 - Decreased Mission Completion Rates
 - Compressor Stalls and Blade Failures
 - Increased Fuel Consumption / Emissions

SAFETY \downarrow
READINESS \downarrow
COST \uparrow

Impact on Engines with Coating



2022 hrs \approx 40 months
Time-On-Wing



NO Blade Curling \Rightarrow
NO Failures

- Engine power retention
 - Blade structural integrity
- \downarrow
- Increased Service Time
 - Decreased Field and Depot Maintenance
 - Increased airfoil reuse during maintenance
 - Increased Mission Completion Rates
 - Safe Engine Operations
 - Decreased Fuel Consumption / Emissions

SAFETY \uparrow
READINESS \uparrow
COST \downarrow

I've got the
Power!

